



Upute za montažu


CE IP44




1




2




3




4



5



6



7



Proverite jesu li svi senzori udaljeni najmanje 200 mm od čvrste površine uključujući zidove.
Preporučuje se, da so vsi senzori oddaljeni vsaj 200 mm od katere koli trdne površine, uključno s stenami.
Please ensure all sensors are at least 200mm away from any solidsurface including walls.